

City of Taunton - Cost Estimation for Polling Locations

City Priorities

Priority 1: Program Access
Priority 2: Safety
Priority 3: Approach and Entrance
Priority 4: Access to Goods and Services
Priority 5: Toilet or Bathing Rooms
Priority 6: Additional Access

*Cost Estimate Notes:

- Cost of design is not included
- Does not include costs when note indicates future work
- Labor cannot be estimated for all remedies
- There is no cost noted when it's presumed to be a maintenance issue.
Estimates are intended as a guide to budgeting access modifications and are not intended to be absolutely comprehensive or definitive.

** 'Dependent on Distance'

Each linear foot of 3 foot wide asphalt costs \$13. Each case requires the City to determine the actual distance to be covered.

The total calculation does not include these costs.

Information Provided by Institute for Human Centered Design										Information Provided by City of Taunton				
FACILITY	REFERENCE #	FB WORK ORDER #	ELEMENT	ISSUE / PHYSICAL BARRIER	LOCATION WITHIN FACILITY	CITY PRIORITY	PRIORITY FOR BARRIER REMOVAL	ACTION FOR BARRIER REMOVAL	ESTIMATED COST OF BARRIER REMOVAL	PROJECT START DATE	PROJECT COMPLETION DATE	RESPONSIBLE FOR BARRIER REMOVAL	BARRIER REMOVED	X
2 Liberty Christian Center	6-134,6-132,6-133		Entrance Door	Doorway at-grade but transition > 1/2"	1A	Priority 3	Approach & Entrance	Repair threshold at door, secure walk-off mat.	\$500.00			City Clerk		
4 Liberty Christian Center	6-130		Parking	# designated accessible ____ no access aisle (if not parallel space) no van-accessible space (if parking lot provided) <i>notes -for aisles not level > 2.08%</i>	1A	Priority 3	Approach & Entrance	Provide designated accessible parking spaces at a level area closer to the entrance.	\$2,610.00			City Clerk		
6 Liberty Christian Center	6-129		Sidewalks + Walkways	no accessible route provided from sidewalks to entrance	1A	Priority 3	Approach & Entrance	Maintain perimeter sidewalks to be level and slip-resistant.	Dependent on distance			City Clerk		
7 Westville Congregational Parish HS	6-135		Entrance Door		1B	Priority 3	Approach & Entrance	Adjust door pressure and replace threshold with a lower threshold.	\$350.00			City Clerk		
8 Westville Congregational Parish HS	6-179		Parking	# designated accessible ____ access aisle does not connect to accessible route van-accessible space + aisle- inadequate dimensions	1B	Priority 3	Approach & Entrance	Relocate accessible parking to the most level area and as close to the accessible entrance as possible. Mount signs at 60" above the ground, and ensure that one space is van accessible.	\$2,610.00			City Clerk		
9 Westville Congregational Parish HS	6-137		Sidewalks + Walkways		1B	Priority 3	Approach & Entrance	Air ramp, secure mat, level end of ramp, and ensure there is an accessible route from accessible parking area.	Dependent on distance			City Clerk		
10 Westville Congregational Parish HS	6-138		Sidewalks + Walkways		1B	Priority 3	Approach & Entrance	Make sure pavement is uniformly level on entrance route.	Dependent on distance			City Clerk		
11 Westville Congregational Parish HS	6-136		Sidewalks + Walkways	no accessible route provided from sidewalks to entrance Sidewalks poorly maintained and unusable	1B	Priority 3	Approach & Entrance	If construction is ongoing during polling even, ensure that the sidewalks barriers lead pedestrians to an accessible route to the front entrance.	\$0.00			City Clerk		
12 Westville Congregational Parish HS	6-180		Sidewalks + Walkways	no accessible route provided from sidewalks to entrance Sidewalks poorly maintained and unusable	1B	Priority 3	Approach & Entrance	If construction is ongoing during polling even, ensure that the sidewalk barriers lead pedestrians to an accessible route to the front entrance.	\$0.00			City Clerk		
13 Fitzsimmons Arms Community Hall (CoA)	6-140 a		Entrance Door	Doorway at-grade but transition > 1/2"	2A	Priority 3	Approach & Entrance	replace threshold with a lower threshold.	\$350.00	2016		City Clerk		
14 Fitzsimmons Arms Community Hall (CoA)	6-140 b		Entrance Door	Door too heavy	2A	Priority 3	Approach & Entrance	Adjust door pressure.	\$350.00	2016		City Clerk		
15 Fitzsimmons Arms Community Hall (CoA)	6-139		Sidewalks + Walkways		2A	Priority 3	Approach & Entrance	Repair deteriorated surfaces of walkway.	Dependent on distance			City Clerk		
15 Fitzsimmons Arms Community Hall (CoA)	6-141		Voting Area	Accessible voting table separated from general area / route AutoMARK Privacy Hood not attached Paper tray not in ready (out) position	2A	Priority 1	Program Access	Provide accessible voting features in as integrated a manner as possible, and not overlapping with staff areas. Provide a sturdy lightweight chair and an automark privacy hood.	\$350.00	2016		City Clerk		
16 Temporary City Hall	6-142		Sidewalks + Walkways		2B	Priority 3	Approach & Entrance	Repair excessive cross slopes	Dependent on distance	2016		City Clerk		
21 Temporary City Hall	6-182		Voting Area	Headphones not attached / provided AutoMARK Privacy Hood not attached Accessible voting table separated from general area / route	2B	Priority 1	Program Access	Provide accessible voting features in as integrated a manner as possible. Clear route of pole-mounted objects and ensure there is a 36" wide clear route. Provide a sturdy chair and privacy hood and headphones.	\$350.00	2016		City Clerk		
22 E. Pole Elem. School - 3A and B	pic in narrative has no #		Election Systems and Software (ES&S) AutoMARK	Accessible table not along accessible route AutoMARK not along accessible route	3A and 3B	Priority 1	Program Access	Provide accessible voting features in as integrated a manner as possible. Clear route of pole-mounted objects and ensure there is a 36" wide clear route. Provide a sturdy chair and privacy hood and headphones.	\$350.00	2016		City Clerk		
23 E. Pole Elem. School -	6-112		Voting Area	Accessible voting table separated from general area / route AutoMARK Privacy Hood not attached Chair provided at AutoMARK table, but not secure (for example, light folding chairs are not secure b/c they move easily on contact)	3A and 3B	Priority 1	Program Access	Provide accessible voting features in as integrated a manner as possible. Clear route of pole-mounted objects and ensure there is a 36" wide clear route. Provide a sturdy chair and privacy hood and headphones.	\$350.00	2016		City Clerk		
26 Joseph Martin School	6-116		Parking	spaces +/-or aisles not level > 2.08% spaces not on shortest route to entrance	4A	Priority 3	Approach & Entrance	ensure that accessible parking spaces are close to entrance and don't have excessive slopes	\$1,740.00	2016		City Clerk		
27 Joseph Martin School	6-114		Sidewalks + Walkways	Sidewalks poorly maintained and unusable	4A	Priority 3	Approach & Entrance	Address excessive cross slopes.	Dependent on distance	2016		City Clerk		
29 Joseph Martin School	6-123		Voting Area	Accessible voting table separated from general area / route AutoMARK Privacy Hood not attached Chair provided at AutoMARK table, but not secure (for example, light folding chairs are not secure b/c they move easily on contact)	4A	Priority 1	Program Access	Provide accessible voting features in as integrated a manner as possible. Provide a sturdy chair, and privacy hood.	\$350.00	2016		City Clerk		
31 East Taunton Elem. School	6-121, 6-120		Parking	spaces +/-or aisles not level > 2.08% access aisle does not connect to accessible route accessible route provided from parking to entrance	4B	Priority 3	Approach & Entrance	Regrade or relocate accessible parking spaces to be on a level area and as close to the entrance as possible. Ensure that access aisle connects to an accessible route.	\$3,480.00	2016		City Clerk		
33 East Taunton Elem. School	6-122		Election Systems and Software (ES&S) AutoMARK		4B	Priority 4	Access to Goods and Services	Ensure that there is a privacy hood at accessible voting stations.	\$100.00	2016		City Clerk		
35 East Taunton Elem. School	6-124		Election Systems and Software (ES&S) AutoMARK	Accessible voting station Knee clearance < 27"	4B	Priority 4	Access to Goods and Services	When setting up portable voting tables, adjust height so that there is at least 27" of clear space under the table.	\$50.00	2016		City Clerk		
36 Hopewell Elementary School	6-148		Parking - Curb ramp	curb ramp landings > 2.08% ramp cross slopes > 2.08% ramp slope exceeds 8.3% %	5A	Priority 3	Approach & Entrance	Address the excessive cross slope and the slope at the ramp.	Dependent on distance			City Clerk		

38	Hopewell Elementary School	6-147		Sidewalks + Walkways		5A	Priority 3	Approach & Entrance	Provide edge protection for ramp and repair 1.5" gap at end of ramp.	\$710.00			City Clerk		
39	Hopewell Elementary School	6-149		Sidewalks + Walkways		5A	Priority 3	Approach & Entrance	Install a visible and audible intercom, replace threshold with lower threshold, secure mats.	\$2,584.00			City Clerk		
44	Hopewell Elementary School	6-150		Sidewalks + Walkways		5A	Priority 3	Approach & Entrance	Move any protruding objects and provide a privacy hood. Repair deteriorated walkway so that it is smooth, level and slip resistant with slopes not exceeding 5% and cross slopes not exceeding 2.08%. Repair ramp to include a level top landing, and repair excessive bevel at the bottom of the ramp.	\$150.00	2016		City Clerk		
45	Joseph Chamberlain Elementary School	6-181		Sidewalks + Walkways	Sidewalks poorly maintained and unusable no accessible route provided from sidewalks to entrance no accessible route provided from parking to entrance	5B	Priority 3	Approach & Entrance		Dependent on distance	2016		City Clerk		
46	Craig C. Sherman Cntr (DPW)	6-156		Sidewalks + Walkways	no accessible route provided from sidewalks to entrance Sidewalks poorly maintained and unusable	6A	Priority 3	Approach & Entrance	Include info for voters to let them know that the facility has a large parking lot with 4 accessible parking spaces. Update voters on sidewalk access from the nearby bus routes in the description.	Dependent on distance/cost of media.	2016		City Clerk		
47	Leddy School	6-158, 6-157		Sidewalks + Walkways	no accessible route provided from parking to entrance no accessible route provided from sidewalks to entrance poorly maintained and unusable	6B	Priority 3	Approach & Entrance	Ensure that the sidewalk alterations around the perimeter of the School are completed and provide a compliant accessible route to the accessible entrance from nearby streets and sidewalks.	Dependent on distance	2016		City Clerk		
49	Mulcahey School	6-159		Sidewalks + Walkways		7A	Priority 3	Approach & Entrance	Resurface the exterior entry way so that running slopes don't exceed 5% and cross slopes do not exceed 2.08%.	Dependent on distance			City Clerk		
50	Mulcahey School	6-160		Sidewalks + Walkways		7A	Priority 3	Approach & Entrance	Prop open existing entry door.	\$0.00			City Clerk		
52	Bennett School	6-126		Election Systems and Software (ES&S) AutoMARK		7B	Priority 1	Program Access	Locate voting equipment so that door maneuvering clearance is adequate.	\$50.00	2016		City Clerk		
53	Bennett School	6-127		Election Systems and Software (ES&S) AutoMARK		7B	Priority 1	Program Access	Repair walkway so that cross slopes and running slopes are accessible.	Dependent on distance	2016		City Clerk		
54	Bennett School	6-128		Election Systems and Software (ES&S) AutoMARK		7B	Priority 1	Program Access	Provide accessible voting features in as integrated a manner as possible. Provide a sturdy chair, and privacy hood.	\$350.00	2016		City Clerk		
55	Benjamin Friedman School	6-171		Parking	# designated accessible ____ # of spaces ____ (total) access aisle does not connect to accessible route	8A	Priority 3	Approach & Entrance	Repair cross slopes at accessible parking spaces and walkways. Consider providing tactile strips where the traffic intersects with pedestrian paths.	Dependent on distance	2016		City Clerk		
56	Benjamin Friedman School	6-172		Sidewalks + Walkways	no accessible route provided from parking to entrance	8A	Priority 3	Approach & Entrance	Consider providing tactile strips where the traffic intersects with pedestrian paths.	Dependent on distance	2016		City Clerk		
57	North Taunton Baptist Church	6-164		Entrance Door		8B	Priority 2	Safety	Secure walkoff mats	\$200.00	2016		City Clerk		
58	North Taunton Baptist Church	6-175		Entrance Door		8B	Priority 3	Approach & Entrance	Pave strip leading to entrance ramp and repair excessive slopes along entry route.	Dependent on distance			City Clerk		
60	North Taunton Baptist Church	6-178		Entrance Door	No sign at inaccessible door to accessible entrance	8B	Priority 3	Approach & Entrance	Provide a directional sign	\$260.00	2016		City Clerk		
62	North Taunton Baptist Church	6-174		Sidewalks + Walkways		8B	Priority 3	Approach & Entrance	Relocate vote sign so that it is out of the 36" accessible route required for entering the building.	\$50.00	2016		City Clerk		
63	North Taunton Baptist Church	6-163		Sidewalks + Walkways	Sidewalks poorly maintained and unusable no accessible route provided from sidewalks to entrance	8B	Priority 3	Approach & Entrance	Maintain perimeter sidewalks to be level and slip-resistant.	Dependent on distance			City Clerk		

TOTAL**

\$18,244.00